HARS OHIO 31-CAMD

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Cincinnati, Ohio

Historic American Buildings Survey Charles R. Strong, District Officer 5700 Carev Tower, Cincinnati, Ohio

C.M.P DEHNISON (Officers' Quarters and Guard-House) Hamilton County, Ohio

Owner. J. Haglin, Perintown, Ohio. Officers' building used as store room and barn by tenant flarmer. Guard-house converted into a small residence.

Date of Erection. 1804 to 1815.

6 時間計畫

Builder. Christian Waldschmidt.

Present Condition. Officers' Quarters very dilapidated. It has been stripped of practically all its trim and interior doors and partitions. Chair rail, stair rail, mantels, etc. have almost disappeared—burned, for the most part, as firewood. The Guard-House has been completely renovated. Valls, joists, and roof-rafters are original porions.

<u>Bumber of Stories.</u> Officers! Quarters---- Dvo and one-half. Guard-House-----Two.

Materials of Construction. Exterior walls and Coundations of indigenous rock. Columns, beams, joists, and rafters of oak. Yellow pine floors. Foplar trim. Tood shingle roof. Interior partitions of wood.

Other Existing Records. Photographs made during Civil Var period in the hands of Miss Marcia Buckingham of Camp Dennison, Chio.

Additional Data. In this valley bordering the Little Liumi River approximately sixty-thousand soldiers were mustered in and out of the service. Their tents, artillery range, etc. were spread over a considerable area. The building then used as a hospital is now a barn. The reservoir has been stripped of its original brick links.

Compiled by-

Charles R. &

DATA NOT COLUMN STATE OF COLUMNS

CHRISTIAN WALDSCHMIDT HOUSE Addendum to:

Camp Dennison, Officer's Quarters 7567 Glendale-Milford Road Camp Dennison Hamilton County Ohio HABS OFFID 31-CAMD

**PHOTOGRAPHS** 

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127